



NO. N 91-37-2-1

To the following Permittee or Operator:

Name GENWAL COAL CO.Mine CRANDALL CANYON MINE ☐ Surface ☒ Underground ☐ OtherCounty EMERY State UTAH Telephone (801) 687-9813Mailing Address P.O. Box 1201, Huntington UT 84528State Permit No. ACT/015/032Ownership Category ☐ State ☐ Federal ☐ Fee ☒ MixedDate of inspection 2/28/91 to 3/1/91, 19Time of inspection 8:30 to 5:00 ☐ a.m. ☒ p.m. to 8:00 to 11:00 ☒ a.m. ☐ p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** ☐ **is not** ☐ expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling 3/15/91 Time of service/mailling 3:00 ☐ a.m. ☒ p.m.

Permittee/Operator representative

Title

Signature

Priscilla Burton

Division of Oil, Gas & Mining representative

Priscilla Burton

Signature

Reclamation Soils Specialist

Title

37

Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

DOGM/NOV-1

an equal opportunity employer

11/85

certified P074979 039

notice of violation



NOTICE OF VIOLATION NO. N 91-37-2-1

Violation No. 1 of 1

Nature of violation

Hindrance

Provisions of act, regulations or permit violated

R614-301-421, Coal mining will be conducted in compliance with
Utah statutes and regulations.

Portion of operation to which notice applies

Crandall Canyon load-out and Genwal Coal Co as a whole.

Remedial action required (including any interim steps)

Notify the Bureau of Air Quality of production in exceedence of the
current permit, submit a copy to the Division. Provide Division
Inspectors with a current copy of the Air Quality Permit, dated 6/15/88.
Include the most current Air Quality permit in App 11-1, Vol 3 of the
Mining and Reclamation Plan

Abatement time (including interim steps)

April 11, 1991



Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

DRH
#6

ADDENDUM TO INSPECTION REPORT

GENWAL COAL CO.

PERMIT ACT\015\032

Page 3 of 4

DATE of INSPECTION: 2/28/91

h. Genwal Coal Co. is not in compliance with its Air Quality Permit. Violation number 91-37-2-1 is being issued for the following reasons.

The State Dept of Health, Bureau of Air Quality (BAQ) has received information from the Division concerning Genwal's proposed upgrading of the load-out, not from Genwal Coal Co. On 1/28/91 the BAQ wrote Genwal to acknowledge the receipt of the information from the Division. The BAQ has considered the information as a "Notice of Intent."

According to the BAQ, Genwal's production level was 352,000 Tons of coal in August 1990 (a rolling 12 month figure). BAQ does not have current tonnage reports from Genwal Coal Co. Genwal must inform the BAQ of their current production level.

The Air Quality permit that Genwal has in its files is not the most current. BAQ has issued Genwal a modification to the 10/85 Air Quality permit allowing a crusher with the processing capacity for 449,000 Tons. This modification was issued 6/15/88. This modification must be available to inspectors.

PERMIT ACT\015\032

Page 4 of 4

DATE of INSPECTION: 2/28/91

6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL

For sediment pond sludge, the regulations pertaining to the disposal of excess spoil (R614-301-745 and R614-301-542.720) or acid/toxic wastes apply (R614-301-542.730 and R614-301-553.252).

Copies of this report:

Mailed to: Brian Smith - OSM, Allen Childs - Genwal Coal Co.

Given to: Daron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number: Christelle Burton, #37

Date: 3/11/91